

United States of America
Department of Transportation Federal Aviation Administration
Supplemental Type Certificate
Number ST01474SE

This certificate, issued to: **TASS, Inc.**
 17530 NE Union Hill Road, Suite 120
 Redmond, WA 98052-3340

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product - Type Certificate Number: A16WE
 Make: The Boeing Company
 Model: 737-700 Series

Description of the Type Design Change: Installation of the Rockwell Collins High Frequency Communication System in accordance with Master Drawing List TASS-ANZ-03-ABMDL, Revision E, dated November 4, 2004, or later FAA approved revisions.

Limitations and Conditions: Approval of this change in type design applies to the above model aircraft identified within the above master drawing list. This approval should not be extended to other aircraft of this model on which other previously approved modifications are incorporated unless it is determined that the interrelationship between this change and any of those other previously approved modifications will introduce no adverse effect upon the airworthiness of the aircraft. A copy of this Certificate must be maintained as part of the permanent records for the modified aircraft.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: July 2, 2004

Date reissued:

Date of issuance: November 9, 2004

Date amended:



By direction of the Administrator

(Signature)

Acting Manager, Seattle Aircraft Certification Office
(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

This certificate may be transferred in accordance with FAR 21.47.